



**MEDCOENERGI**

Jakarta, 8 Juli 2008  
MEI198 /Dir DD/VII/08

Kepada Yth. To

**Badan Pengawas Pasar Modal dan Lembaga Keuangan ("Bapepam-LK")**

Gedung Baru Departemen Keuangan Lt. 4

Jl. Lapangan Banteng Timur No. 1

Jakarta

U.p. Attn. : **Bapak Dr. Ahmad Fuad Rahmany**  
Ketua *Chairman*

**PT Bursa Efek Indonesia ("BEI" / "IDX")**

Gedung Bursa Efek Indonesia Tower I, Lantai 4

Jl. Jend. Sudirman Kav. 52-53

Jakarta

U.p. / Attn. : **Bapak Erry Firmansyah**  
Direktur Utama / *President Director*

Perihal *Subject* : Laporan Keterbukaan Informasi PT Medco Energi Internasional Tbk  
Insiden Kebocoran Gas Pada Sumur Petar-1 di Blok South Sumatra Extension (SSE),  
Sumatra Selatan  
*Disclosure Report of PT Medco Energi Internasional Tbk*  
*Gas flow in Petar-1 Well, South Sumatra Extension (SSE) Block, South Sumatra*

Dengan hormat,


*Dear Sir,*

Dalam rangka memenuhi Peraturan BAPEPAM No. X.K.1, mengenai Keterbukaan Informasi yang Harus Segera Diumumkan Kepada Publik dan Peraturan BEJ No. I-E mengenai Kewajiban Penyampaian Informasi dan menunjuk laporan keterbukaan informasi kami, PT Medco Energi Internasional Tbk ("MedcoEnergi" atau "Perseroan") memberitahukan bahwa:

*In compliance with the BAPEPAM's Rule No. X.K.1, regarding Disclosure Made to Public Immediately and the JSX's Rule No. I-E regarding the Requirement to Disclose Information, PT Medco Energi International Tbk. ("MedcoEnergi" or the "Company") would like to inform you that:*

- Pada tanggal 27 Juni 2008 terjadi aliran gas di sumur Petar-1 di Blok SSE yang dioperasikan oleh PT Medco E&P Indonesia ("MEPI"), anak perusahaan yang dimiliki sepenuhnya oleh Perseroan.
- *On June 27, 2008 a gas flow incident has occurred in Petar-1 well in SSE Block, which is operated by PT Medco E&P Indonesia ("MEPI"), a wholly owned subsidiary of the Company.*
- Tidak terdapat korban jiwa dalam kejadian ini dimana lokasi sekitar sumur adalah semak belukar dan berada jauh dari pemukiman penduduk.
- *There were no casualties in this incident as the location of the well is mainly bushes and is secluded from the residential areas.*
- MEPI segera melakukan tindakan penanggulangan
- *MEPI took some precautions to overcome the gas*

5-



## MEDCOENERGI

untuk mengatasi aliran gas dari sumur tersebut dan akan mencari tahu penyebab dari kebocoran tersebut.

- Setelah MEPI melakukan pengecekan dengan *gas detector* pada radius +/- 500 meter dari sekitar sumur, tidak ditemukan kerusakan lingkungan dan tidak ada gas berbahaya yang keluar dari sumur tersebut.

Kami akan melaporkan lebih lanjut perkembangan penanggulangan insiden ini ke Bapepam-LK segera.

### Latar Belakang


Lokasi sumur Petar-1 terletak di Desa Petar Dalam, Kecamatan Sungai Rotan, Kabupaten Muara Enim, Provinsi Sumatera Selatan. Sumur Petar-1, South Sumatra Extension Blok ini dibor pertama kali tahun 1986 oleh PT Stanvac Indonesia, operator terdahulu, dan sumur telah ditutup untuk sementara sejak tahun 1986. Sumur Petar-1 merupakan sumur yang telah ditutup sehingga tidak ada aktifitas produksi pada lokasi ini.

### Dampak Keuangan

Kerugian atas berhentinya produksi dan penanganan atas insiden ini belum dapat kami perhitungkan. Kami perkirakan kerugian yang kami alami tidak akan berdampak material terhadap keuangan Perseroan di tahun 2008.

Demikian kami sampaikan pemberitahuan ini, atas perhatian Bapak kami ucapkan terima kasih.

Hormat kami *Sincerely Yours,*

  
**Darmoyo Doyoatmojo**

Direktur Utama *President Director*

*flow from the well with investigation continues to find the root of cause.*

- *After MEPI conducted some inspections including using a gas detector within radius of +/- 500 meter from the well, no environmental damage and no hazardous gas emerged from the well as a result of this incident.*

*We will report further the development in handling this incident to Bapepam-LK immediately.*

### Background

*Petar-1 well is located in Petar Dalam Village, Sungai Rotan Sub-district, Muara Enim Regency, South Sumatra Province. Petar-1 well in South Sumatra Extension Block was drilled for the first time in 1986 by PT Stanvac Indonesia, the previous operator of the block, and had been shut down also in 1986. The Sumur Petar-1 is a suspended well and therefore no production activities in this location.*

### Financial Impact

*We are not able to calculate the loss from the gas flow and the handling of this incident yet. We estimate that the loss will not materially affect the Company's financial in 2008.*

*Thank you for your attention.*

Tembusan Kepada Yth. C.c:

- Ibu Ir. Nurhaida, MBA, Ka.Ro. PKP Sektor Riil, Bapepam
- Bapak Eddy Sugito, Direktur Pencatatan PT Bursa Efek Indonesia
- Komisaris dan Direksi PT Medco E&P Indonesia
- Komisaris dan Direksi PT Medco Energi Internasional Tbk